

# H3E630 Mounting Hardware

# Thru Bolt for Metal or Wood Door




| ТҮРЕ | BOLT<br>SIZE | DRILL SIZE |
|------|--------------|------------|
| 1    | 1/4 - 20     | 9⁄32"      |
| 1HD  | 5/16 - 18    | 11⁄32"     |

# Thru Bolt for Glass Door



| ТУРЕ | BOLT SIZE | DRILL SIZE<br>GLASS |
|------|-----------|---------------------|
| 15   | 1/4 - 20  | 5⁄8"                |
| 15HD | 5/16 - 18 | 5⁄8"                |

# Surface Concealed for Metal Door




| ТҮРЕ | BOLT SIZE | DRILL SIZE<br>METAL |
|------|-----------|---------------------|
| 6R   | 1/4 - 20  | 3/8" X 1-1/4" DP    |
| 6RHD | 5/16 - 18 | 1/2" X 1-1/4" DP    |

# Thru Bolt for Metal or Wood Door 1-3/4" Decorative Cap

| TYPE | BOLT<br>SIZE | DRILL SIZE |
|------|--------------|------------|
| 12   | 1/4 - 20     | 9⁄32"      |
| 12HD | 5/16 - 18    | 11/32"     |


# Surface Concealed for Metal Door



Minimum diameter of pull is 3/4"

| ТҮРЕ | BOLT SIZE | THREAD SIZE   |
|------|-----------|---------------|
| 6    | 1/4 - 20  | 1/4 - 20 TAP  |
| 6HD  | 5/16 - 18 | 5/16 - 18 TAP |

# Surface Concealed for Wood Door



Minimum diameter of pull is 3/4"

| ТҮРЕ | BOLT SIZE | DRILL SIZE<br>WOOD |
|------|-----------|--------------------|
| 8    | 1/4 - 20  | 1-1/4" DP          |
| 8HD  | 5/16 - 18 | 1-1/4" DP          |